Table of Contents

Particulars	Paragraph	Page		
Preface		V		
Executive Summary		vii		
Chapter I : Introduction				
Background	1.1	1		
Rationale for selecting the topic	1.2	1		
Audit Objectives	1.3	2		
Audit Criteria	1.4	2		
Scope and Methodology of Audit	1.5	3		
Acknowledgement	1.6	3		
Audit Findings	1.7	3		
Chapter II: Responsibilities of different departments and agencies				
Pollution Control Boards at the Centre and State	2.1	5		
State Bio-diversity Board	2.2	7		
Other Departments and agencies	2.3	8		
Chapter III: Water Pollution				
Use based classification of surface water not made	3.1	9		
Inadequate analysis of water	3.2	10		
Water Quality Monitoring Stations not classified	3.3	10		
High pollution in major rivers/ponds in Guwahati	3.4	12		
Ground Water quality	3.5	15		
Contamination of ground water with Fluoride & Arsenic	3.5.1	16		
Inferior quality of piped drinking water	3.6	17		
Absence of Sewage units	3.7	18		
Untreated industry effluent released	3.8	19		
Recommendations	3.9	20		
Chapter IV: Air Pollutio	on			
Inadequate monitoring of air pollutants	4.1	21		
Unscientific location of Air Quality Monitoring Stations	4.2	22		
Ambient Air Quality at different Stations of Guwahati	4.3	23		
Industrial Emission	4.4	24		

Performance Audit on Environmental Degradation in the greater Guwahati Area with special emphasis on the role of the Pollution Control Board, Assam'

i

Industries operating without valid Consent for Operation	4.4.1	24
Inadequate inspection of Industries	4.4.2	25
Emission of Particulate Matter (PM) in excess of standard	4.4.3	26
Joint physical inspection of industries	4.4.4	26
Continuous Stack Emission Monitoring System not installed	4.4.5	27
Vehicular emission	4.5	28
Position of Motor Vehicles on road	4.5.1	29
Joint Physical Inspection of Vehicle Pollution Emission Testing Centres	4.5.2	29
Inadequate monitoring of Auto emission testing Stations	4.5.3	30
High Benzene Level near the Petrol/Diesel Retail Station	4.6	31
Recommendations	4.7	32
Chapter V: Municipal Solid Wa	ste (MSW)	
Previous Audit Findings	5.1	33
Quantity of MSW generated, collected, treated & disposed off	5.2	34
Unhygienic collection and storage of MSW	5.3	35
Transportation of MSW	5.4	37
Partial treatment of MSW	5.5	37
Leachate at MSW Dumping Site	5.6	38
Monitoring of Air Quality at MSW Dumping Site	5.7	39
Ground Water Quality at MSW Dumping Site	5.8	39
Recommendations	5.9	40
Chapter VI: Bio Medical Wast	e (BMW)	
HCEs functioning without obtaining authorisation	6.1	41
HCEs functioning without BMW treatment facilities	6.2	42
Monitoring of Veterinary Institutions	6.3	43
Monitoring of PCBA under BMW Rules	6.4	43
Quantity of BMW generated, treated and disposed off	6.5	44
Common Bio Medical Waste Treatment Facilities	6.6	45

Performance Audit on Environmental Degradation in the greater Guwahati Area with special emphasis on the role of the Pollution Control Board, Assam'

ii

(CBWTF)			
Segregation, packaging, transportation and storage of BMW at CBWTF	6.7	45	
Treatment of BMW at CBWTF	6.8	46	
Handling of BMW at CBWTF	6.9	46	
Physical Inspection of Health Care Establishments (HCEs)	6.10	47	
Advisory Committee on Bio-Medical Wastes	6.11	48	
Recommendations	6.12	49	
Chapter VII: Other Wastes			
Hazardous Waste	7.1	51	
Plastic Waste	7.2	52	
Battery waste	7.3	53	
E-waste	7.4	55	
Recommendations	7.5	56	
Chapter VIII: Conclusion		57	
Appendices		59	