

## TABLE OF CONTENTS

|  | Paragraph | Page |
|--|-----------|------|
| Preface  |           | v    |
| Executive Summary  |           | vii  |
| <b>CHAPTER I - INTRODUCTION</b>                                |           |      |
| Floods of 2015   | 1.1       | 1    |
| Incidence of rainfall  | 1.2       | 2    |
| Statutory and Institutional framework for flood management     | 1.3       | 3    |
| Departments and agencies audited                               | 1.4       | 4    |
| Audit Objectives   | 1.5       | 5    |
| Audit Criteria   | 1.6       | 5    |
| Scope and Coverage of Audit                                    | 1.7       | 6    |
| Previous Audits  | 1.8       | 6    |
| Audit Methodology  | 1.9       | 7    |
| Sampling   | 1.10      | 7    |
| <b>CHAPTER II – PLANNING</b>                                   |           |      |
| Planning for regulation of land use                            | 2.1       | 9    |
| Policies and Plans focusing on flood prevention and moderation | 2.2       | 19   |
| Construction activities along water bodies                     | 2.3       | 22   |
| Non-adherence to land use planning                             | 2.4       | 28   |
| Analysis   | 2.5       | 35   |

|  | Paragraph | Page |
|--|-----------|------|
| <b>CHAPTER III - MANAGEMENT OF WATER BODIES</b>                        |           |      |
| Deficiencies in increase in storage capacity of water bodies           | 3.1       | 37   |
| Non-implementation of project for restoration and protection of lakes  | 3.2       | 44   |
| Incomplete river restoration works                                     | 3.3       | 44   |
| Analysis   | 3.4       | 47   |
| <b>CHAPTER IV - ENCROACHMENTS</b>                                      |           |      |
| Encroachments contributing to the floods                               | 4.1       | 49   |
| Encroachment in tanks  | 4.2       | 50   |
| Encroachment of rivers   | 4.3       | 51   |
| Encroachments of water bodies by local bodies                          | 4.4       | 55   |
| Structural hindrances in Adyar River course                            | 4.5       | 58   |
| Analysis   | 4.6       | 61   |
| <b>CHAPTER V - DRAINAGE SYSTEM IN CHENNAI METROPOLITAN AREA</b>        |           |      |
| Flood protection works   | 5.1       | 63   |
| Micro drainage system  | 5.2       | 73   |
| Storm Water Drain network of Greater Chennai Corporation               | 5.3       | 77   |
| Storm Water Drain network in suburban areas                            | 5.4       | 81   |
| Clogging of storm water drains due to unauthorised entry of sewage     | 5.5       | 84   |
| Pre-monsoon preparedness work  | 5.6       | 85   |
| Non-adherence to instructions on supervising desilting of water bodies | 5.7       | 87   |

|   | Paragraph | Page |
|---|-----------|------|
| Flood mitigation measures in Adyar River  | 5.8       | 88   |
| Inundations in suburban areas of Chennai  | 5.9       | 98   |
| Analysis  | 5.10      | 100  |
| <b>CHAPTER VI - DISASTER MANAGEMENT</b>   |           |      |
| Deficiencies in the institutional framework                                     | 6.1       | 103  |
| Shortfalls in capacity building for disaster management                         | 6.2       | 105  |
| Deficiencies in functioning of Emergency Operation Centre                       | 6.3       | 106  |
| Rescue operations   | 6.4       | 108  |
| Relief work   | 6.5       | 109  |
| Inadmissible expenditure from SDRF on restoration works in flood affected areas | 6.6       | 116  |
| Non-receipt of Utilisation Certificate  | 6.7       | 116  |
| Analysis  | 6.8       | 117  |
| <b>CHAPTER VII - MONITORING</b>   |           |      |
| Monitoring the implementation of Second Master Plan                             | 7.1       | 119  |
| Absence of monitoring in leasing of land  | 7.2       | 122  |
| Analysis  | 7.3       | 122  |
| <b>CHAPTER VIII - CONCLUSION</b>  |           |      |
| Lessons learnt  | 8.1       | 123  |
| Lessons not learnt  | 8.2       | 124  |
| Conclusion  | 8.3       | 125  |

## APPENDICES

| Appendix No. | Details  | Page |
|--------------|--|------|
| 2.1          | Satellite images of CMA  | 129  |
| 2.2          | Joint Field Inspection Report of layout approvals along water body in Kundrathur Panchayat Union (PU), Kundrathur Town Panchayat (TP) and Poonamallee PU | 131  |
| 2.3          | Reclassification of Open Space and Recreation (O&R) zone to others   | 134  |
| 5.1          | Details of missing links   | 136  |
| 5.2          | Physical and Financial Progress of works under TNSUDP as on 31 August 2016   | 138  |
| 5.3          | Areas in selected suburban areas affected by flood   | 140  |
| 5.4          | Details of SWD constructed partially in Pallavapuram Municipality  | 141  |
| 5.5          | Maintenance of water bodies in selected Zones/Municipalities and Town Panchayats   | 142  |
| 5.6          | Details of inflow and surplus discharge from Chembarambakkam tank  | 143  |
| 7.1          | Achievement against service level bench mark   | 144  |
|              | Glossary of Abbreviations  | 145  |